

: P M A C



	P M A C - A	P M A C - B	P M A C - C	P M A C - D	P M A C - E
	C r 1 2 Mo V				
	H R C 6 0 - H R C 6 2				
	3 4 5 6 8 1	1 2 1 3 1 5 1 8	3 0 4 0 mm (M)	5 0 6 0 mm (M)	7 0 8 0 mm (M)
	M)	(M)			
	3 0 mm (N)	4 0 mm (N)	5 0 mm (N)	5 5 mm (N)	6 0 mm (N)
	4 3 * 9 3 mm (L * H)	5 3 * 1 2 0 mm (L * H)	7 3 * 1 3 3 mm H)	9 5 * 1 1 5 * 1 5 0 mm (L * H)	1 2 7 * 1 1 5 3 * 1 8 0 mm H) 1 8 0 * 1 8 0 mm (L
(K g)	0 . 7 5 K g	1 . 2 K g	3 . 8 K g 6 . 3 K g	1 4 K g 2 0 K g	3 0 K g 4 0 K g