

: PMS



. Cr 1 2 Mo V

	P MS - A	P MS - B	P MS - C	P MS - D	P MS - E	PMS - F	P MS - G
	C r 1 2 Mo V						
	HRC60-HRC62						
	3 × 3 / 4 × 4 / 5 × 5 / / 1 0 × 1 0 mm	12×12 /15×15 /16 /20×20 mm	22×22 /25×2 /30×30 mm	3 2 × 3 2 / 3 5 × 3 / 4 0 × 4 0 mm	50×50 /60×60 /70	81-150 mm()	151- 200mm()
	20 mm	3 0 mm	4 0 mm	4 5 mm	55/60/65 mm	6 0 mm	6 0 m m
	4 3 × 9 3 mm	5 3 × 1 2 0 mm	7 3 × 1 3 3 mm	88×150mm	98×150 mm/ 118×1 38×180 mm	1 6 0 × 1 4 0 m	2 2 0 × 1 6 0 ı
(Kg	0.65	1. 2	2. 4	4.8	7.3/11.4/20	25 k g - 40	45kg-80